Building Technologies

BOSCH

| From | Our Reference<br>BT-SC/ESG2 | Tel | Singapore<br>27 March 2019 |
|---|---|---|---|

**Patch procedure**

Issue      A recently discovered security vulnerabilities affect the AEC
software in cases of video integration.
This patch is according to CVE-2019-6957 and CVE-2019-6958.

Topic      **Upgrading AEC2.1 to VideoSDK 6.32**

Description    This document describes how to apply the patch to update
AEC2.1 installation to VideoSDK 6.32.
**Patch version:** AEC2.1 Video plugins version 6.32.0099 - 2.0.0.4

**To upgrade this ActiveX/VideoSDK patch**

1. Log into the AEC 2.1
2. Upload the ActiveX/VideoSDK patch file into the controller at
   "System->AdvanceSettings->VideoSDK"

**Note**
1. The patch file is quite big (>34MB), so it will take 4-8 minutes to upload.
   Once uploaded successfully it will prompt a message that VideoSDK is updated and it
   will show the version mentioned above.
2. After applying the patch, please close the browser and access the panel again to install
   the latest ActiveX and VideoSDK.
3. This patch can be uploaded in AEC2.1.8.5 version onwards.